

---

| <b>Patrón (Standard)</b> | <b>UBP (UUT)</b> | <b>Error (Error)</b> | <b>Exactitud (Accuracy)</b> | <b>Incertidumbre (Uncertainty)</b> |             |
|--------------------------|------------------|----------------------|-----------------------------|------------------------------------|-------------|
| 60 RPM                   | 60.00 RPM        | 0.00 RPM             | ± 0.022 RPM                 | ±                                  | 9.5E-03 RPM |
| 600 RPM                  | 600.0 RPM        | 0.0 RPM              | ± 0.22 RPM                  | ±                                  | 5.8E-02 RPM |
| 6000 RPM                 | 6000 RPM         | 0.0 RPM              | ± 2.2 RPM                   | ±                                  | 5.8E-01 RPM |
| 60000 RPM                | 60000 RPM        | 0.0 RPM              | ± 13 RPM                    | ±                                  | 9.0E-01 RPM |
| 99960 RPM                | 99959 RPM        | -1.0 RPM             | ± 21 RPM                    | ±                                  | 9.3E-01 RPM |